AIR VACUUM VALVE



NOTES

- THE ABOVE GROUND COVER SHALL BE THOROUGHLY CLEANED AND PAINTED WITH ONE COAT OF PRIMER AND ONE COAT OF SAFETY YELLOW ENAMEL.
- INSTALL PIPE BARRICADES AS DIRECTED BY RHWCO
- ANY BARE STEEL SHALL BE WRAPPED IN 10 MIL TAPE OR EQUIVELANT.
- COMPLETE ASSEMBLY SHALL BE PLUMB.

1. AN APPROVED AIR/VAC
2. 8" X 2" BRASS NIPPLE
3. 2" BRASS BALL VALVE
4. 6" X 2" BRASS NIPPLE
5. PACK JOINT CTS X FEMALE THREAD
6. 2" TYPE K COPPER TUBING
7. 2" PACK JOINT CTS 90
8. 2" CORP STOP MIP X PACK JOINT
9. 2" BRONZE SADDLE